

Quote Number: 2018-282027 Account ID: 0001090320

Proposal For:

VEOLIA WATER Douglas Thornberry 501 E SANTA ANA AVE BLOOMINGTON, CA 92316

Phone: 909-877-2752

douglas.thornberry@veolia.com

James Moore

Evoqua Water Technologies

N19W23993 Ridgeview Pkwy, Suite 200

Waukesha, WI 53188 Phone: 262-521-8368

james.a.moore@evoqua.com

ITEM PRICING SUMMARY

Item Number	Description	Reference Number	Qty	Net Price	Ext. Price
W2T835903	PANEL VIEW 7 10" HMI SCREEN		1	\$4,520.00	\$4,520.00
W3T6313	electrical field tech to hook up new HMI, check out electrical panel for start up.		1 EA	\$9,200.00	\$9,200.00
	contractor to repair Dystor Contractor to adjust/reinstall membrane cable, remove replace (3) air gas hoses, with assist of the Evoqua field tech, bring the Dystor from the standby mode to operational status. (1) trip (3) days on site.		1 EA	\$44,000.00	\$44,000.00
W3T6313	field tech to assist & direct Dystor repair		1 EA	\$9,200.00	\$9,200.00

Total net price:

\$66,920.00

Proposal Notes

we are looking at the week of 12/17/2018 for contractor & tech to perform this work. Mechanical

- Air Filter is plugged and dry rotted/falling apart
- Only 1 PVRV is on the gas standpipe, the second one is off because that is where they have the hose attached.
 The pallet for the PVRV will need to be replaced/rebuilt and a few more lead weights are required since this one is mostly destroyed from venting.
- There is a blind flange on the air purge piping (PVC) that is cracked and should be replaced.
- Overflow piping needs to be capped off as mentioned above.
- Temporary hose is cloth and has many holes with duct tape holding it together. When this is put into operation they will not need this hose anymore.

Electrical

- The HMI screen is destroyed and no longer works.
- SCADA hookup is not complete. There are wires connected to the contacts from the PLC output. I do not know if they need additional tags from the PLC program

Page 1 10-11-2018



Quote Number: 2018-282027 Account ID: 0001090320

Due to extreme volatility in steel costs, prices quoted in this proposal will be adjusted to reflect changes in the Metal and Metal Products Index (MMPI) published by the U.S. Department of Labor, Bureau of Labor Statistics. The most recent published MMPI is 222.4 for April 2018.

If the MMPI exceeds 226.9 at the time the Equipment is released for manufacture, then the price will be increased by the same percentage as the MMPI exceeds 226.9

Please provide tax exempt certificate with purchase order.

Our Manufacturer Rep in your area is:

Representative:

Steve Wallace

Company:

TW ASSOCIATES INC - MISCOWATER SOUTHWEST

List Address:

27101 Burbank, Suite B

Foothill Ranch, CA, 92610

Phone:

Email:

swallace@miscowater.com