141 S. Palm Rehabilitation Scope

1)	Roof Replacement Roof condition is poor that requires replacement.	\$	5,000
2)	Window Replacement Windows are single-pane non-energy efficient. Replace 12 windows at \$500 per window.	\$	5,600
3)	Electrical Upgrade Electrical requires updating inside the building.	\$	5,000
4)	New Flooring Includes any required repairs.	\$	5,000
5)	Interior cosmetic for walls and ceiling and framing Includes interior painting and wall repairs.	\$	10,000
6)	Demolition work	\$	5,000
7)	Exterior painting and landscaping	\$	5,000
8)	Bathroom Rehabilitation and ADA Standards Bathroom condition is poor and non-ADA complaint.	\$	10,000
9)	Exterior ADA-Access Improvements ADA access includes ramp and parking.	\$	5,000
10)	ADA-Interior Door Interior doors require resizing to meet ADA requirements. At \$800 per door.	\$	5,600
11)	HVAC HVAC requires testing. It may or may not require replacement. If replaced, the minimum cost is \$7,500. The \$500 cost is for testing.	\$	500
12)	Misc. For unknown work.	\$	5,000
13)	Asbestos Asbestos exists in ceiling that probably can be capsulated at no cost. However, if asbestos requires removal, then minimum cost is \$10,000.	?	
	Sub-Total - Direct Construction Cost (Non-Prevailing Wage):	\$	66,700
	Contingency (20%)	\$	13,340
	Building Permit Fee	\$	775
	Construction Plan and Scope Preparation	\$	5,000
	Total - Rehabilitation Cost (Non-Prevailing Wage):	\$	85,815
	Sub-Total - Direct Construction Cost (Prevailing Wage at 30%):	\$	86,710
	Contingency (20%)	\$	17,342
	Building Permit Fee	\$	775
	Construction Plan and Scope Preparation	\$	5,000
	Total - Rehabilitation Cost (Prevailing Wage):	\$	109,827