



**CITY OF RIALTO
LIABILITY
CLAIM FOR DAMAGES
TO PERSON OR PROPERTY**

CITY CLERK'S DATE STAMP
CITY OF RIALTO
2026 FEB 13 PM 3: 53

1. Claims for death, injury to person, or to personal property must be filed not later than six (6) months after the occurrence (Gov. Code §911.2).
2. Claims for damages to real property must be filed not later than one (1) year after the occurrence (Gov. Code §911.2).
3. READ ENTIRE CLAIM FOR BEFORE FILING
4. ATTACH SEPARATE SHEETS, IF NECESSARY, TO GIVE FULL DETAILS

RETURN TO:
Rialto City Clerk's Office
Mail: 150 S. Palm Ave., Rialto, CA 92376
Address: 290 W. Rialto Ave., Rialto, CA 92376

report reference
932601882

CLAIMANT INFORMATION:

Geraldo Rodriguez
FULL NAME

DATE OF BIRTH _____

HOME ADDRESS INCLUDING CITY, STATE & ZIP _____
HOME TELEPHONE NO. Cell

BUSINESS ADDRESS INCLUDING CITY, STATE & ZIP _____
BUSINESS TELEPHONE NO. _____

ADDRESS AT WHICH CLAIMANT DESIRES TO RECEIVE NOTICES OR COMMUNICATIONS REGARDING THIS CLAIM (if different from home address provided above): _____

1. WHEN DID DAMAGE OR INJURY OCCUR? DATE: 2/12/26 TIME: 5:15pm-6pm AM PM

2. PLACE OF ACCIDENT (OCCURRENCE) BE SPECIFIC - Describe fully and (if applicable) locate on diagram on reverse side of this sheet. Where appropriate, give street names and addresses, measurements and landmarks.
Vehicle was parked in the front of 1049 N. Clifford Ave Apt. A Rialto CA, 92376, corner of Shamrock St & Clifford Ave.

3. HOW DID DAMAGE OR INJURY OCCUR? Per Vehicle was parked; officer: he was backing up his car (reverse) in between a tow truck and my parked vehicle when he made contact with his rear passenger side to my rear driver side back end.

4. WERE POLICE AT THE SCENE? YES NO WERE PARAMEDICS AT THE SCENE? YES NO

5. WHAT PARTICULAR ACT OR OMISSION DO YOU CLAIM CAUSED THE INJURY OR DAMAGES? Give the name of the city/town employee causing the injury or damage, if known.
Rialto officer Supervisor arrived to the scene, took report & photos card provided to me with the following info. Date: 2/11/26
Comment: 932601882, officer: V. Herrera, badge No. 110

6. GIVE TOTAL AMOUNT OF CLAIM Include estimate of amount of any prospective injury or damage \$ 9,662.82

HOW WAS THE ABOVE AMOUNT COMPUTED? Be specific, list doctor bills, repair estimates, etc. Please attach 2 estimates.

DAMAGES INCURRED TO DATE:

Item/Date: <u>2017 Chevrolet Camaro, back driver rear</u>	Amount: \$ <u>8,802.17</u>
Item/Date: <u>2-wk car rental, but while damages are fixed.</u>	Amount: \$ <u>860.65</u>

Full replacement.

TOTAL AMOUNT CLAIMED AS OF PRESENTATION OF THIS CLAIM:

\$ 9,662.82

ESTIMATED PROSPECTIVE DAMAGES, AS FAR AS KNOWN:

All major

Item/Date: Full (L) driver replacement & paint - ~~1/15/2023~~

Amount: \$ 8,900.17

Item/Date: Full (L) driver back replacement & paint - Islas - ~~1/15/2023~~

Amount: \$ 7,305.65

TOTAL ESTIMATED AMOUNT PROSPECTIVE DAMAGES:

\$ 9,662.82

(car repairs & rental)

7. WITNESSES TO DAMAGE OR INJURY List all persons known to have information (attach additional pages, if necessary)

NAME: N/A

NAME: _____

ADDRESS: _____

ADDRESS: _____

TELEPHONE: () _____

TELEPHONE: () _____

8. IF INJURED, PROVIDE NAME, CONTACT INFORMATION AND DATE/TIME DOCTOR(S) OR HOSPITAL(S) VISITED:

NAME: N/A

NAME: _____

ADDRESS: _____

ADDRESS: _____

TELEPHONE: () _____

TELEPHONE: () _____

DATE: _____ TIME: _____ AM PM


DATE: _____ TIME: _____ AM PM

9. PLEASE READ THE FOLLOWING CAREFULLY:

For all vehicle accident claims, place on the following diagram, the names of streets, including NORTH, EAST, SOUTH AND WEST directions. Indicate place of accident by "X" and by showing house numbers or distances to street corners.

If a city/town vehicle was involved, designate by letter "A" location of the City/Town vehicle when you first saw it, and by "B" location of yourself or your vehicle when you first saw City/Town vehicle; location of City/Town vehicle at time of accident by "A-1" and location of yourself or your vehicle at the time of the accident by "B-1" and the point of impact by "X".

⇒ NOTE: IF THE DIAGRAM BELOW DOES NOT FIT THE SITUATION, PLEASE ATTACH A PROPER DIAGRAM SIGNED BY THE CLAIMANT.



I HAVE READ THE FOREGOING CLAIM AND KNOW THE CONTENTS THEREOF; AND CERTIFY THAT THE SAME IS TRUE OF MY OWN KNOWLEDGE EXCEPT AS TO THOSE MATTERS WHICH ARE HEREIN STATED UPON MY INFORMATION AND BELIEF; AND AS TO THOSE MATTERS I BELIEVE THEM TO BE TRUE.

I CERTIFY (OR DECLARE) UNDER PENALTY OF PERJURY THAT THE FOREGOING IS TRUE AND CORRECT.

SIGNATURE OF CLAIMANT OR AGENT

Caraldo Rodriguez

TYPE OR PRINT NAME

owner of vehicle / claimant.

RELATIONSHIP TO CLAIMANT

2/13/24.

DATE

NOTE: PRESENTATION OF A FALSE CLAIM IS A FELONY (CA PENAL CODE 72) RETURN CLAIM TO: RIALTO CITY CLERK'S OFFICE - 150 S. PALM AVE., RIALTO, CA 92376

Claim for Property Damage – Collision Report Summary

On February 12, 2026, between approximately 5:15 p.m. and 6:00 p.m., a vehicle collision occurred in front of my residence located at 1049 North Clifford Avenue, Apartment A, Rialto, California 92376, at the corner of West Shamrock Street (300 W) and North Clifford Avenue (1000 N). At the time of the incident, my vehicle, a **2013 Chevrolet Camaro, license plate number** _____ was legally parked and unoccupied.

According to the on-scene statement provided by Officer V. Herrera (Badge #110), he was operating a **Ford patrol vehicle, license plate number 1256929, site/unit number R517**, and was reversing between my parked Camaro and a tow truck positioned across from my vehicle. While backing into the space between both vehicles, Officer Herrera’s patrol vehicle made contact with the rear driver’s side of my vehicle using the rear driver’s side of his vehicle. As a result, my vehicle sustained damage to the rear driver-side back end.

Shortly thereafter, a supervising officer from the Rialto Police Department arrived at the scene, conducted an on-site review, and took photographs and an official report. I was issued a courtesy notice card documenting the incident with the following details: Date: 02/12/2026; Digital Numeric Reference: 932601882; Officer: V. Herrera; Badge Number: 110.

In support of this claim, I have attached two independent auto repair appraisals detailing the collision-related damages. Additionally, I have included three vehicle rental estimates based on a minimum projected repair timeframe of approximately two weeks, as indicated by the repair businesses providing the appraisals.

Furthermore, I have provided a diagram clearly identifying the exact parked position of my vehicle and the point of impact, along with multiple photographs documenting the damage and scene conditions. Taken together, these materials substantiate the location, mechanism, and extent of the collision and resulting property damage.

Accordingly, this summary is submitted as part of my formal claim for property damage reimbursement related to this incident.

Geraldo Rodriguez
2/13/26

CITY OF RIALTO
2026 FEB 13 PM 3:53
RECEIVED
CITY CLERK

FREE
ESTIMATES



Manager

(951) 334-4192

(951) 565-7660

300 S Sycamore Ave. Building B Rialto CA 92376



Islas Auto Body
 300 S Sycamore Ave Building B, Rialto, CA 92376-6579
 Office: (951) 904-0479
 islasautobody@gmail.com
 islasautobody.com

Estimate ID
 26696165
 Original

Owner
GERALDO RODRIGUEZ

Appraiser
Julio Islas
 islasautobody@gmail.com

Classification
 None

RECEIVED
 CITY CLERK
 2026 FEB 13 PM 3:53
 CITY OF RIALTO

Loss Type
Unknown

Deductible
Unknown

2013 Chevrolet Camaro LT 2 Door Coupe 3.6L 6 Cyl Gas Injected 6 Speed Auto Trans RWD

VIN
Unknown

Mitchell Service Code
911210

Options

Air Conditioning	Alum/Alloy Wheels	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)	Automatic Headlights
Auxiliary Input	Bluetooth Wireless Connectivity	Cloth Seat	Cruise Control	Daytime Running Lights
Driver-Front Air Bag	Electric Defogger	Electronic Stability Control	First Row Bucket Seat	Fog Lights
Keyless Entry System	Leather Steering Wheel	Left-Curtain Air Bag	MP3 Player	Passenger-Front Air Bag
Power Door Locks	Power Driver Seat	Power Passenger Seat	Power Remote Mirror	Power Steering
Power Windows	Rear Bench Seat	Rear Spoiler	Remote Decklid Or Tailgate Release	Satellite Radio
Second Row Side Airbag With Head Protection	Side Airbags	Steering Wheel Mounted Audio Control	Telematic Systems	Tilt Steering Wheel
Tire Pressure Monitoring System	Traction Control/Electronic System			

GERALDO RODRIGUEZ | 2013 Chevrolet Camaro LT

Parts Profile
 AM and QR Parts

Parts Profile Version
 2.0

Line #	Description	Operation	LABOR			PART				
			Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Front Door										
1	101137 L Frt Door Outside	Blend	Refinish	1.0 C	2.3	Existing				
2	101251 L Frt Rear View Mirror	Remove / Install	Body	INC#	0.8	Existing				
3	101253 L Frt Otr Door Belt Moulding	Remove / Install	Body	0.9#	0.9	Existing				
4	103657 L Frt Otr Door Belt Moulding	Remove / Replace	Body	INC#	0.2	New	20965831	1	\$214.00*	Yes
5	101148 L Frt Door Trim Panel	Remove / Install	Body	INC	0.4	Existing				

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
6	101154 L Frt Otr Door Handle	Remove / Install	Body	0.3	0.3	Existing				
Back Window										
7	100195 Back Window Glass	Remove / Install	Glass	2.5#	2.5	Existing				
Side Body										
8	100884 L Side Body Panel Assembly -S	Remove / Replace	Body	20.1#	20.1	New	19370675	1	\$2,455.87*	Yes
9	AUTO L Side Body Panel Complete	Refinish Only	Refinish	6.6 C	6.6	Existing				
10	AUTO L Quarter Panel Edge	Refinish Only	Refinish	0.5 C	0.5					
11	AUTO L Add For Pillar	Refinish Only	Refinish	0.5 C	0.5					
12	AUTO L Add To R&L/R&R Side Curtain Air Bags-M	Remove / Replace	Mechanical	0.8#	0.8					
13	AUTO L Add To R&L/R&R Side Air Bag Sensor -M	Remove / Replace	Mechanical	0.4	0.4					
14	100961 L Cowl/Dash Trim Panel	Remove / Install	Body	INCr	0.2	Existing				
15	100971 L Frt Upr Quarter Trim Panel	Remove / Install	Body	INCr	0.2	Existing				
16	100987 L Rear Upr Quarter Trim Panel	Remove / Install	Body	INCr	0.2	Existing				
17	100995 L Lwr Quarter Trim Panel	Remove / Install	Body	INCr#	0.3	Existing				
18	AUTO Rear Seat Assy	Remove / Install	Body	INC	0.5					
Luggage Lid										
19	100004 Luggage Lid Outside	Blend	Refinish	0.9 C	2.1	Existing				
20	101127 Luggage Lid Spoiler	Remove / Install	Body	0.5#	0.5	Existing				
Rear Bumper										
21	101374 Rear Bumper Cover	Repair	Body	4.0*#	2.5	Existing				
22	AUTO Rear Bumper Cover	Refinish Only	Refinish	2.9 C	2.9	Existing				
Additional Costs & Materials										
23	AUTO Paint/Materials	Additional Cost							\$756.00	Yes
24	AUTO Shop Materials	Additional Cost							\$5.00*	Yes
25	AUTO Hazardous Waste Disposal	Additional Cost							\$5.00*	Yes
Additional Operations										
26	AUTO Clear Coat	Additional Operation	Refinish	3.9	0.0				\$0.00	
27	933003 Tint Color	Additional Operation	Refinish	0.5*	0.0				\$0.00	
28	933007 Feather, Prime & Block	Additional Operation	Refinish	0.0	0.0				\$0.00	
29	933021 De-Nib And Finesse	Additional Operation	Refinish	3.0*	0.0				\$0.00	
30	933018 Mask For Overspray	Additional Operation	Refinish	1.0*	0.0				\$10.00*	

* Judgment Item

C Included in Clear Coat Calculation

T Included in Two Tone Calculation
 # Labor Note Applies
 d Discontinued by Manufacturer

A Included in Clear Coat and Two Tone Calculation
 r CEG R&R Time Used for this Labor Operation
 [] Verify the part number and price before ordering

Estimate Totals

Labor	Units	Rate	Sublet	Add'l Amount	Totals
Body Labor	25.8	\$75.00			\$1,935.00
Refinish Labor	20.8	\$65.00		\$10.00	\$1,362.00
Glass Labor	2.5	\$65.00			\$162.50
Mechanical Labor	1.2	\$120.00			\$144.00
Total Labor	50.3				\$3,603.50
				Taxable	\$3,603.50
				Tax 0.0000%	\$0.00
				Non-Taxable	\$0.00
				Pre-Tax Discount 0.00%	\$0.00
				Labor Total	\$3,603.50
Parts		Amount			
Taxable Parts		\$2,669.87			\$2,669.87
				Parts Adjustments	\$0.00
				Tax 7.7500%	\$206.91
				Non-Taxable	\$0.00
				Pre-Tax Discount 0.00%	\$0.00
				Parts Total	\$2,876.78
Costs		Amount			
Paint Materials		\$756.00			\$756.00
Shop Materials		\$5.00			\$5.00
Other Additional Costs		\$5.00			\$5.00
Paint Materials:				Taxable	\$766.00
- Refinish Units: 16.8 units				Tax 7.7500%	\$59.37
- Rate: \$45.00				Non-Taxable	\$0.00
- Rate Max: 99.9 units				Pre-Tax Discount 0.00%	\$0.00
- Additional Rate: \$0.00				Costs Total	\$825.37
Shop Materials:					
- Rate: \$5.00					
Gross Totals		Amount			
Gross Total		\$7,305.65			\$7,305.65
				Taxable	\$7,039.37
				Tax	\$266.28
				Non-Taxable	\$0.00
				Pre-Tax Discount 0.00%	\$0.00
				Gross Total	\$7,305.65
Adjustments		Amount			
Total Customer Responsibility					\$0.00
				Net Estimate Total	\$7,305.65

Disclaimer: For your protection California law requires the following statement to appear on this form. Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

Estimate Event Log

Job Created 2/13/2026 01:19 PM
Estimate Started 2/13/2026 01:20 PM
Estimate Printed 2/13/2026 01:25 PM
Estimate Committed Estimate Not Committed
Estimate Retrieval ID 1009251406

Jose Sanchez ALL MAGIC PAINT & BODY

 909-434-0500 / 800-61-Magic

 Jose@AllMagicAuto.com



FONTANA OFFICE

www.AllMagicAuto.com

18150 Foothill Blvd
Fontana, Ca. 92335
909-434-0500
or 800-61-Magic

Additional locations to serve you:
Norco
Moreno Valley
Eastvale

ALL MAGIC PAINT & BODY FONTANA

18150 Foothill Blvd, Fontana, CA 92335
Phone: (909) 434-0500
FAX: (909) 822-1602

Workfile ID: 7c32bdae
State ID: 264790144-00001
Federal EPA: PT0040524
State EPA: CAL000451880
BAR: 296862

Preliminary Estimate

Customer: Rodriguez, Geraldo

Written By: Jose Sanchez

Insured: Rodriguez, Geraldo
Type of Loss:
Point of Impact: 08 Left Qtr Post (Left Side)

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Rodriguez, Geraldo

Inspection Location:
ALL MAGIC PAINT & BODY FONTANA
18150 Foothill Blvd
Fontana, CA 92335
Repair Facility
(909) 434-0500 Business

Insurance Company:
CUSTOMER PAY

RECEIVED
CITY CLERK
2026 FEB 13 PM 3:53
CITY OF RIALTO

VEHICLE

2013 CHEV Camaro LT1 2D CPE 6-3.6L Gasoline Direct Injection RED

VIN: Interior Color: BLK Mileage In: Vehicle Out:
License: Exterior Color: RED Mileage Out:
State: CA Production Date: 9/2012 Condition: Good Job #:

TRANSMISSION

6 Speed Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Message Center
Steering Wheel Touch Controls
Telescopic Wheel

RADIO

AM Radio
FM Radio
Stereo
Search/Seek

Auxiliary Audio Connection
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System
Hands Free Device

SEATS

Cloth Seats
Bucket Seats

Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Traction Control
Stability Control
Rear Spoiler
Power Trunk/Liftgate

Preliminary Estimate

Customer: Rodriguez, Geraldo

2013 CHEV Camaro LT1 2D CPE 6-3.6L Gasoline Direct Injection RED

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		PILLARS, ROCKER & FLOOR					
2	Repl	LT Uniside assy	19370675	1	1,834.78	25.0	7.3
3	*	Add for Clear Coat					2.9
4	R&I	LT Rocker molding w/o ZL1				0.8	
5	R&I	LT Drip molding				0.4	
6	Repl	LT Drip molding rivet	11611651	7	55.23		
		Note: 7 of these are required. 1 TIME USE.					
7	R&I	LT W/S pillar trim black				Incl.	
8	R&I	LT Cowl trim				0.1	
9	R&I	LT W'strip on body				Incl.	
10		DOOR					
11	*	Blnd LT Outer panel					<u>1.1</u>
12	R&I	LT Belt molding				0.2	
13	R&I	LT R&I mirror				0.3	
14	R&I	LT Handle, outside				0.4	
15	R&I	LT R&I trim panel				0.5	
16		BACK GLASS					
17	R&I	Back glass GM				2.0	
18	#	Repl Urethane Kit		1	60.00		
19		QUARTER PANEL					
20	R&I	LT Pressure vent				0.1	
21	R&I	LT Wheelhouse liner				Incl.	
22	Repl	Fuel pocket	22765851	1	43.47	0.3	
		Note: PARTS: Part cannot be reused/reinstalled.					
23	R&I	Fuel door painted				0.3	
24	*	Blnd Fuel door painted					<u>0.2</u>
25	Repl	LT Stone guard	20951963	1	12.88	0.2	
26	R&I	LT Quarter glass GM				Incl.	
27	#	Subl Urethane Kit		1	30.00 X		
28	R&I	LT Upper qtr trim black				Incl.	
29	R&I	LT Lower qtr trim				Incl.	
30		REAR BUMPER					
31		O/H bumper assy				3.4	
32		Deduct for Rear Bumper R&I				-1.7	
33	* <>	Rpr Bumper cover w/o park sensor				<u>6.0</u>	3.2
34		Overlap Major Non-Adj. Panel					-0.2
35	*	Add for Clear Coat					0.6
36		VEHICLE DIAGNOSTICS					
37	*	Subl Pre-repair scan		1	<u>72.00</u> X m		
38	*	Subl Post-repair scan		1	<u>72.00</u> X m		
39	*	Subl DTC Reset		1	<u>187.20</u> X m		
40		MISCELLANEOUS OPERATIONS					
41	*	Repl Cover car for Overspray		1	<u>5.00</u>	0.2	

Preliminary Estimate

Customer: Rodriguez, Geraldo

2013 CHEV Camaro LT1 2D CPE 6-3.6L Gasoline Direct Injection RED

42	*	Repl	Cover car for Primer	1	5.00	0.2
43	#		Color Tint	1		0.5
44	#		Color Sand and Buff	1		1.0
45	#		D&R Battery	1		0.2
46	#		Cover for Interior	1	3.00	0.2
47	#		Seam Sealer	1	25.00	1.0
48	#		Weld thru Primer	1	10.00	0.5
49	#		Flex Additive	1	8.00	
50	#		Restore Corrosion Protection	1	10.00	0.3
51	#		Mask Windshield	1		0.3
SUBTOTALS					2,433.56	42.7
						15.1

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			2,072.36
Body Labor	42.7 hrs @	\$ 90.00 /hr	3,843.00
Paint Labor	15.1 hrs @	\$ 90.00 /hr	1,359.00
Paint Supplies	15.1 hrs @	\$ 60.00 /hr	906.00
Miscellaneous			361.20
Subtotal			8,541.56
Sales Tax	\$ 2,978.36 @	8.7500 %	260.61
Grand Total			8,802.17

MyPriceLink Estimate ID / Quote ID:

1451696769724325888 / 151069531

Preliminary Estimate

Customer: Rodriguez, Geraldo

2013 CHEV Camaro LT1 2D CPE 6-3.6L Gasoline Direct Injection RED

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO APPEAR ON THIS FORM. ANY PERSON WHO KNOWINGLY PRESENTS FALSE OR FRAUDULENT INFORMATION TO OBTAIN OR AMEND INSURANCE COVERAGE OR TO MAKE A CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON.

THIS ESTIMATE IS FOR REPAIRS TO MEET VEHICLE MANUFACTURER AND INDUSTRY STANDARDS. AS THE CUSTOMER, IT IS YOUR RESPONSIBILITY TO CONTACT THE THIRD-PARTY PAYOR FOR PAYMENT OF THE REPAIRS YOU HAVE AUTHORIZED.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED:

MOTOR ABBREVIATIONS/SYMBOLS: D=DISCONTINUED PART, A=APPROXIMATE PRICE. LABOR TYPES: B=BODY LABOR, D=DIAGNOSTIC, E=ELECTRICAL, F=FRAME, G=GLASS, M=MECHANICAL, P=PAINT LABOR, S=STRUCTURAL, T=TAXED MISCELLANEOUS, X=NON TAXED MISCELLANEOUS. CCC ONE: ADJ=ADJACENT, ALGN=ALIGN, A/M=AFTERMARKET, BLND=BLEND, CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION, D&R=DISCONNECT AND RECONNECT, EST=ESTIMATE, EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY, INCL=INCLUDED, MISC=MISCELLANEOUS, NAGS=NATIONAL AUTO GLASS SPECIFICATIONS, NON-ADJ=NON ADJACENT, O/H=OVERHAUL, OP=OPERATION, NO=LINE NUMBER, QTY=QUANTITY, RECOND=RECONDITION, REFN=REFINISH, REPL=REPLACE, R&I=REMOVE AND INSTALL, R&R=REMOVE AND REPLACE, RPR=REPAIR, RT=RIGHT, SECT=SECTION, SUBL=SUBLET, LT=LEFT, W/O=WITHOUT, W/_=WITH/_ SYMBOLS: #=MANUAL LINE ENTRY, *=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED], **=DATABASE LINE WITH AFTERMARKET, N=NOTES ATTACHED TO LINE. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

""CURE TIME"" MEANS THE LENGTH OF TIME THAT, PER THE ADHESIVE MANUFACTURER, THE WINDSHIELD ADHESIVE NEEDS TO CURE UNTIL THE WINDSHIELD CAN PROPERLY FUNCTION AS A SAFETY DEVICE PURSUANT TO THE FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND THE VEHICLE MANUFACTURER'S SPECIFICATIONS.

Preliminary Estimate

Customer: Rodriguez, Geraldo

2013 CHEV Camaro LT1 2D CPE 6-3.6L Gasoline Direct Injection RED

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1CD10, CCC Data Date 02/09/2026, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

CITY OF RIALTO

2028 FEB 13 PM 3:53

RECEIVED
CITY CLERK

Rialto Police Courtesy Notice

Date 2/12/26 Time

Day of Week

Comment 932681882

Officer V. Hernandez

Badge No. 110

CONTACT RIALTO PD.-(909) 820-2550 FOR FURTHER INFORMATION

(Over)

CITY OF RIALTO
2025 FEB 13 PM 3:53
RECEIVED
CITY CLERK

MSM...

1041DCD02

MARIA C TORRES RODRIGUEZ

NAIC# 22268

CALIFORNIA
CALIFORNIA EVIDENCE OF LIABILITY INSURANCE

Infiniti Insurance Company
3760 River Run Drive Birmingham, AL 35243
(800) 782-1020

5515846

YEAR
2013

MAKE/MODEL
CHEVROLET/CAMARO

VEHICLE ID NUMBER

Company
Infiniti Insurance Company

POLICY NUMBER
10146233301

NAME & ADDRESS OF INSURED
MARIA C TORRES RODRIGUEZ

Policy Holder
MARIA C TORRES RODRIGUEZ

EFFECTIVE DATE
07/28/2026

EXPIRATION DATE
07/28/2026

DRIVER(S)

MARIA C TORRES RODRIGUEZ
GERALDO RODRIGUEZ
ANTHONY RODRIGUEZ
PAIOLA RODRIGUEZ TORRES

Policy Number
10146233301
Effective
01/28/2026

This policy complies with Sections 16056 or 16500.5 of the California Vehicle Code.

CITY OF RIALTO

2028 FEB 13 PM 3:53

RECEIVED
CITY CLERK

Registration

STATE OF CALIFORNIA - DEPARTMENT OF MOTOR VEHICLES

VALIDATED REGISTRATION CARD

LICENSE NUMBER	REGISTRATION VALID FROM	TYPE	TYPE VEHICLE USE	ENGINE NUMBER	MISC
	12/20/2025 TO 12/20/2026	11	AUTO		K17 40
VEHICLE IDENTIFICATION NUMBER	MAKE	VLF CLASS	*YR	YR MODEL	DATE ISSUED
	CHEV	FH	2013	2013	12/05/2025
BODY TYPE MODEL	MP	AX	WC	UNLADEN / G / CGW	TOTAL FEES PAID
Cp	6				\$173



STICKER INSTRUCTIONS

- 1) CLEAN SURFACE - REMOVE ALL OFF ACCUMULATED STICKERS (WALL NOT STICK IF WET OR DIRTY).
- 2) REMOVE DECAL BY BENDING PAPER ALONG DOTTED LINE.
- 3) LIFT EDGE OF DECAL AND SLOWLY PEEL.
- 4) PLACE STICKER ON REAR PLATE AS SHOWN BELOW.

PEEL HERE

REGISTERED OWNER
RODRIGUEZ GERALDO

LIENHOLDER




Registration Fee: \$173.00
 Credit Card Service Fee: \$2.00
 Title: \$170.27
 Payment Type: VISA
 Account Number: 0000
 Transaction Number: 398-3408271
 Date: 02/13/2025
 Card Card Authorization Number: 185856

W 00000
R 00138
L 00023

VEHICLES:
 in Top Right Corner

MOTORCYCLES ONLY:
 Right Hand of This Wheel



IMPORTANT INSTRUCTIONS ON REVERSE SIDE

Nissan Maxima or similar

Automatic

#1 vehicle car rental



CITY OF RIALTO
RECEIVED
2026 FEB 13 PM 3:53
CITY CLERK

✦✦ It's not too late! You can still upgrade to Luxury for only \$136.78* more. (\$862.29 total)

Upgrade

Vehicle

Edit

Time & Distance 2 Week(s) @ \$ 324.58 / week

\$ 649.16*

Unlimited Mileage

Included

Extras

Add

-

Taxes and Fees

\$ 76.35*

Estimated Total

\$725.51*

#2 Vehicle Car rental

Full Size Elite

Audi A5 Sportback or similar

 Automatic



Vehicle

[Edit](#)

Time & Distance 2 Week(s) @ \$ 375.56 / week

\$ 751.12*

Unlimited Mileage

Included

Extras

[Add](#)

-

Taxes and Fees 

\$ 93.92*

Estimated Total

\$845.04*

 Custom Rate

Standard Pickup

#3 Vehicle Car rental

Toyota Tacoma or similar

 Automatic



✦✦ It's not too late! You can still upgrade to 1/2 Ton Pickup for only \$4.62* more. (\$865.27 total)

Upgrade

RECEIVED
CITY CLERK
2025 FEB 13 PM 3:54
CITY OF RIALTO

Vehicle

Edit

Time & Distance 2 Week(s) @ \$ 380.08 / week

\$ 760.16*

Unlimited Mileage

Included

Extras

Add

Taxes and Fees 

\$ 100.49*

\$860.65

CITY OF RIALTO

2022 FEB 13 PM 3:54

RECEIVED
CITY CLERK

1256929

8011

RIALTO
POLICE

CHRYSLER





